



March 2006

David McNett
11608 Spicewood Pkwy Unit 29
Austin, TX 78750-2650

Re: VIN# LJ82270

Dear BMW Owner:

At BMW of North America we are committed to maintaining a level of automotive and service excellence that exceeds your expectations now and in the future.

BMW has become aware of a potential problem that could affect the Bremi ignition coils durability of certain 2001, 2002 and 2003 BMW models equipped with a Motorsport 3.2 liter engine. Based on our research a small percentage of vehicles will actually develop a problem, which is first indicated by a "Service Engine Soon" light being illuminated, and in some cases by engine rough running.

As a commitment to our customers, and to demonstrate confidence in our product, BMW will extend the warranty for the Bremi ignition coils from 4 years or 50,000 miles to 8 years and unlimited mileage.

The warranty extension for this component applies to the above listed models and is transferable to any subsequent purchaser of these vehicles. This extended warranty is applicable to vehicles registered in all 50 states. Warranty coverage for all other parts is not affected. Warranty terms and conditions can be found in your warranty booklet.

In the unlikely event that the Bremi ignition coils of your vehicle shows the above symptom, please feel free to contact your authorized BMW center to arrange a service appointment.

We sincerely apologize for this inconvenience. If you have any questions, please feel free to contact your authorized BMW center or BMW of North America, through our website at www.bmwusa.com or by calling Customer Relations and Services at (800) 831-1117.

Company
BMW of North America, LLC

BMW Group Company

Address
BMW Plaza
Montvale, NJ
07645-1866

Sincerely,

A handwritten signature in black ink that reads "Alan E. Harris".

Alan E. Harris
Vice President, Aftersales
BMW of North America, LLC